



PEUGEOT 508: 1FET144

Vinnumber:	VF38E9HD8DL028628	Versionname:	508 SW e-HDi Active BMP 115PK Aut.
First Registrationdate:	10/06/2013	Fiscalpower:	
Expertise Mileage:	218037	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2307
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	25/60/16/95 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 1,6 mm	Fr.R.	Michelin: 1,6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1395,34
-------------------	---------

Bumper F L, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Windscreen, Damaged, E - Replace	487,20
----------------------------------	--------



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	502,50
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------

