



**RENAULT Kangoo: 1DRN784**

Vinnumber:	<b>VF1KW24B547707293</b>	Versionname:	<b>KANGOO Authentique FAP</b>
First Registrationdate:	<b>2/08/2012</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>75043</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4314</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 7 mm</b>	Fr.R.	<b>Continental: 7 mm</b>
	Re.L.	<b>Continental: 8 mm</b>	Re.R.	<b>Continental: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1332,49</b>
-------------------	----------------

Wing F L, Scratch(es), LI - Repair and paint (complete)	<b>220,18</b>
---	---------------



Bumper F L, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Bodywork, Not original part, Remove lettering	<b>0,00</b>
---	-------------



Wheel cover F L, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 332,20



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), It - Spot repair 115,56



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Seat cover F L, Worn, Acceptable 0,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Wheel cover R R, Scratch(es), E - Replace 30,00

