


**RENAULT MEGANE GRANDTOUR: 1KVC265**

Vinnumber:	<b>VF1KZ0R0253356059</b>	Versionname:	<b>1.5 DCI 95 TOMTOM EDITION</b>
First Registrationdate:	<b>10/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>125541</b>	Power Kw:	<b>70</b>
Bodytype:		Body color	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3823</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H Steel</b>			
Winter tyres:	Fr.L.	<b>Firestone: 6 mm</b>	Fr.R.	<b>Firestone: 6 mm</b>
	Re.L.	<b>Firestone: 6,5 mm</b>	Re.R.	<b>Firestone: 6,5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	306,28
-------------------	--------

Wing R L, Bad repair, Acceptable	0,00
----------------------------------	------

*No pictures to display*

Wheel cover R R, Broken, E - Replace	30,00
--------------------------------------	-------



Door panel R R, Scratch(es), Smart repair	110,64
---	--------



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Glove compartment lid, Scratch(es), Acceptable 0,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Headlight L, Not functioning (well), Adjust 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Interior, Stain, Cleaning 25,00

