



VOLKSWAGEN Passat: 1ERW870

Vinnnumber:	WVWZZZ3CZDP040487	Versionname:	PASSAT BER Comfortline BMT 105PK
First Registrationdate:	5/03/2013	Fiscalpower:	
Expertise Mileage:	111569	Power Kw:	77
Bodytype:	Berline	Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Grey
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	4	Parking lot:	2720
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L
GPS storage	Central consol F
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1548,34
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Wheel hub cap F L, Missing, E - Replace

5,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bump(s), PDR - Knock out without painting 63,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim F R, Scratch(es), Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Alloy rim R L, Scratch(es), Acceptable 0,00

