



VOLKSWAGEN Golf: 1HUP158

Vinnnumber:	WVWZZZAUZFP023638	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	7/10/2014	Fiscalpower:	
Expertise Mileage:	86775	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2525
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 MS Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	651,60
--------------------------	---------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
--------------------------------------------------------------------	---------------



Bodywork, Not original part, Remove lettering	0,00
------------------------------------------------------	-------------

<i>No pictures to display</i>		
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)		259,80
Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover F R, Scratch(es), E - Replace		30,00
Rearview mirror R complete, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		