



VOLKSWAGEN Polo: 1HKA240

Vinnnumber:	WVWZZZ6RZEY215527	Versionname:	POLO Comfortline DPF
First Registrationdate:	6/08/2014	Fiscalpower:	75PK
Expertise Mileage:	80131	Power Kw:	55
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1104
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/60/15/88 T Steel				
Winter tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	500,68
-------------------	--------

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	24,00
---	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bodywork, Not original part, P - Check	0,00
--	------



Wheel cover R R, Scratch(es), E - Replace

24,00



Door F R, Bump(s), LI - Repair and paint (complete)

302,68

