



VOLKSWAGEN Polo: 1HJV566

Vinnnumber:	WVWZZZ6RZEY213913	Versionname:	POLO Comfortline DPF
First Registrationdate:	5/08/2014	Fiscalpower:	75PK
Expertise Mileage:	99298	Power Kw:	55
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1325
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2952,05
-------------------	----------------

Bonnet, Bump(s), Le - Replace and paint	827,76
---	---------------



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	302,68
---	---------------



Grill, Broken, E - Replace

30,72



Ignition key, Missing, E - Replace

150,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F R, Stain, Cleaning

25,00



Headlight R, Broken, E - Replace

336,00



Front bumper, Bump(s) and scratch(es), E - Replace

418,56



Door F L, Scratch(es), LI - Repair and paint (complete)

254,68



Wing F R, Bump(s), Le - Replace and paint

448,01



Wheel cover R L, Scratch(es), E - Replace

24,00



Rearview mirror L complete, Scratch(es), Smart repair

110,64



Wheel cover F R, Scratch(es), E - Replace

24,00

