


PEUGEOT 508: 1EYQ423

Vinnnumber:	VF38E9HD8DL021574	Versionname:	508 SW e-HDi Active BMP 115PK Aut.
First Registrationdate:	23/04/2013	Fiscalpower:	
Expertise Mileage:	160641	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2820
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	306,80
-------------------	--------

Bonnet, Chemical polution, P - Check	0,00
--------------------------------------	------



Door F L, Bad repair, P - Check	0,00
---------------------------------	------



Door frame R R, Scratch(es), Acceptable 0,00



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Dirty, Chemical cleaning 75,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Reflector, Damaged, E - Replace 20,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80

