



VOLVO S80: 1ESQ819

Vinnnumber:	YV1AS84A1D1172478	Versionname:	S80 BER D2 Kinetic S/S
First Registrationdate:	11/03/2013	Fiscalpower:	115PK
Expertise Mileage:	155338	Power Kw:	85
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4619
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	Tow bar removable
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Continental: 0 mm	Fr.R.	Continental: 5 mm
	Re.L.	Uniroyal: 7,5 mm	Re.R.	Uniroyal: 7,5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	866,46
-------------------	--------

Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	348,09
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00

No pictures to display