



## VOLKSWAGEN Touran: 1FVE706

|                                   |                         |              |                             |
|-----------------------------------|-------------------------|--------------|-----------------------------|
| Vinnnumber:                       | <b>WVGZZ1TZEW035583</b> | Versionname: | <b>TOURAN Trendline BMT</b> |
| First Registrationdate:           | <b>5/11/2013</b>        | Fiscalpower: | <b>Start/Stop 105PK</b>     |
| Expertise Mileage:                | <b>130473</b>           | Power Kw:    | <b>77</b>                   |
| Bodytype:                         |                         | Body color   | <b>Black</b>                |
| Gearbox:                          | <b>MAN 6 VIT</b>        | Paint type   | <b>Metalic</b>              |
| Transmission:                     | <b>Front</b>            | Rims summer  | <b>Aluminium</b>            |
| Fueltype:                         | <b>Diesel</b>           | Oil level    | <b>OK</b>                   |
| Maintenance                       | <b>OK</b>               | Parking lot  | <b>3830</b>                 |
| Battery functioning               | <b>Yes</b>              |              |                             |
| Number of doors                   | <b>5</b>                |              |                             |
| Number of seats                   | <b>7</b>                |              |                             |
| Number head rests                 | <b>7</b>                |              |                             |
| Rims summer                       | <b>Aluminium</b>        |              |                             |
| Category                          | <b>Passenger Car</b>    |              |                             |
| Oil level                         | <b>OK</b>               |              |                             |
| Registration Certificate Car (BE) | <b>Yes</b>              |              |                             |

## Options

|                                |                              |                      |                      |
|--------------------------------|------------------------------|----------------------|----------------------|
| Radio CD                       |                              | Sun Roof electric    |                      |
| GPS storage                    | <b>HD</b>                    | Panoramic roof       |                      |
| GPS storage                    |                              | Central consol F     |                      |
| Windows electric F             |                              | Luggage cover        |                      |
| Windows electric R             |                              | Rear parking sensors |                      |
| Cruise Control                 |                              | Type of Tow bar      | <b>Tow bar fixed</b> |
| Steering wheel multifunctional |                              |                      |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                      |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |                      |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 T LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

## Assistance equipment

|                                      |        |
|--------------------------------------|--------|
| Total cost ex VAT                    | 647,20 |
| Rear window, Scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>        |        |
| Door panel R R, Worn, Acceptable     | 0,00   |
| <i>No pictures to display</i>        |        |
| Bonnet, Chemical polution, P - Check | 0,00   |



Interior, Stain, Cleaning

25,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Smart repair 110,64



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bump(s), PDR - Knock out without painting 111,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door frame R R, Bump(s) and scratch(es), It - Spot repair 115,56

