



VOLKSWAGEN Polo: 1HKA214

Vinnnumber:	WVWZZZ6RZEY193025	Versionname:	POLO Comfortline DPF
First Registrationdate:	6/08/2014	Fiscalpower:	75PK
Expertise Mileage:	88857	Power Kw:	55
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2402
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 253,44

Aerial, Missing, E - Replace 12,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), I I - Repair and paint (complete) 217,44

		
Rear window, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover F R, Scratch(es), E - Replace		24,00



Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rear window, Not original part, P - Check		0,00



Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Electricity circuit, Not functioning (well), P - Check		0,00

