


MERCEDES Vito: 1FNF296

Vinnumber:	WDF63960113826781	Versionname:	VITO 113 B/F SWB 136PK
First Registrationdate:	27/08/2013	Fiscalpower:	
Expertise Mileage:	172876	Power Kw:	100
Bodytype:	Transporter	Body color:	Red
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3706
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Front parking sensors
Windows electric F		Rear parking sensors
Radio multimedia		
Type of headlighting:	Headlighting Halogen	
Type of Lining:	Lining fabrics	
Type of climate control:	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/16/100 T Steel			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Total cost ex VAT	1803,57
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F R, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Missing, E - Replace	22,50



Sliding door R, Accident, Le - Replace and paint	1088,52
--	---------



Trunk door R R, Bump(s), PDR - Knock out without painting 63,00



Dashboard, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bump(s), E - Replace 398,40



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Trunk door R L, Bump(s), Acceptable 0,00

No pictures to display