


**RENAULT Scenic: 1DMQ370**

Vinnumber:	<b>VF1JZ140647344889</b>	Versionname:	<b>SCENIC Energ.Bose Edit.110PK</b>
First Registrationdate:	<b>25/06/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>93117</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Gold</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1632</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b> Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunction	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


**Degree of wear**

	<b>205/55/17/55 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 7 mm</b>	Re.R.	<b>Pirelli: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	305,56
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00




Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Seat cover F L, Tear, Acceptable	0,00
----------------------------------	------

*No pictures to display*

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*