


**RENAULT Grand Scenic: 1FXC479**

|                                   |                          |              |                                             |
|-----------------------------------|--------------------------|--------------|---------------------------------------------|
| Vinnnumber:                       | <b>VF1JZ14M649974099</b> | Versionname: | <b>GRAND SCENIC Energy Intens 5pl.110PK</b> |
| First Registrationdate:           | <b>25/11/2013</b>        | Fiscalpower: |                                             |
| Expertise Mileage:                | <b>112679</b>            | Power Kw:    | <b>81</b>                                   |
| Bodytype:                         |                          | Body color   | <b>Black</b>                                |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                              |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                            |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                                   |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>1411</b>                                 |
| Battery functioning               | <b>Yes</b>               |              |                                             |
| Number of doors                   | <b>5</b>                 |              |                                             |
| Number of seats                   | <b>5</b>                 |              |                                             |
| Number head rests                 | <b>5</b>                 |              |                                             |
| Rims summer                       | <b>Aluminium</b>         |              |                                             |
| Category                          | <b>Passenger Car</b>     |              |                                             |
| Oil level                         | <b>OK</b>                |              |                                             |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                             |

**Options**

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| Radio CD                       |                              | Sun Roof electric    |
| GPS storage                    |                              | Panoramic roof       |
| GPS storage                    | <b>SD</b>                    | Central consol F     |
| Windows electric F             |                              | Luggage cover        |
| Windows electric R             |                              | Rear parking sensors |
| Cruise Control                 |                              |                      |
| Steering wheel multifunctional |                              |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining leather</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/17/95 V LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|               | Re.L.                            | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                                    |                |
|------------------------------------|----------------|
| Total cost ex VAT                  | <b>1665,84</b> |
| Door F R, Scratch(es), Acceptable  | <b>0,00</b>    |
| <i>No pictures to display</i>      |                |
| Seat cover F L, Hole, Smart repair | <b>64,32</b>   |



|                                   |             |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|                                              |             |
|----------------------------------------------|-------------|
| Rearview mirror housing R, Bad repair, Paint | <b>0,00</b> |
|----------------------------------------------|-------------|



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Door F R, Bad repair, Paint 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Maintenance, Maintenance, P - Check 0,00



Windscreen, Scratch(es), E - Replace 487,20



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace 114,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Seat cover F R, Damaged, Smart repair 64,32



Door F L, Bump(s), PDR - Knock out without painting 63,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen trim, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Chemical pollution, Acceptable 0,00

No pictures to display

Windscreen trim, Bump(s) and scratch(es), LI - Repair and paint (partial) 163,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

