



OPEL Zafira: 1FHR514			
Vinnumber:	WOLPE9EM8D2070810	Versionname:	ZAFIRA TOURER ecoFL.Cosmo St/St.130PK
First Registrationdate:	2/07/2013	Fiscalpower:	
Expertise Mileage:	75296	Power Kw:	96
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 0 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Compressor	Yes
Total cost ex VAT	2100,34
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door F R, Bad repair, Acceptable	0,00
----------------------------------	------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Bump(s), PDR - Knock out without painting 63,00



Door R R, Bump(s), PDR - Knock out without painting 82,80



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen trim, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Floor covering F L, Hole, Smart repair 64,32



Door panel R L, Damaged, Smart repair 110,64

