


AUDI A3: 1GCV589

Vinnumber:	WAUZZZ8V9EA109587	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	29885	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1607
Maintenance:	SERVICE IN 29100KM 652D		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	221,00
-------------------	--------

Bonnet, Bump(s), PDR - Knock out without painting	63,00
---	-------










Rearlight L, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Bump(s) and scratch(es), Acceptable	0,00
---	------

<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Roof pillar R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Interior, No damage, Acceptable		0,00
		
Roof, Bump(s), PDR - Knock out without painting		63,00
		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		