



AUDI A6: 1CBC692			
Vinnnumber:	<b>WAUZZZ4G0CN044609</b>	Versionname:	<b>A6 BER Multitr. 204PK Aut.</b>
First Registrationdate:	<b>10/10/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>211737</b>	Power Kw:	<b>150</b>
Bodytype:		Body color	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3714</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

Options			
Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>225/60/16/98 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 1 mm</b>	Fr.R.	<b>Bridgestone: 1 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			4836,65
Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)			264,21



Tailgate, Bump(s), PDR - Knock out without painting	162,00
---	--------



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 150,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Roof pillar R, Bump(s), Acceptable 0,00

No pictures to display

Windscreen, Repaired, Acceptable 0,00



Roof pillar L, Hail damage, LI - Repair and paint (complete) 264,22



Door F L, Missing, F - Replace 50,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Door F R, Bump(s), PDR - Knock out without painting 122,40



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s), Le - Replace and paint 1205,64





Roof, Hail damage, PDR - Hail 1200,00

