



AUDI A3: 1FEK040			
Vinnumber:	<b>WAUZZ8V3EA001062</b>	Versionname:	<b>A3 SB Attraction 105PK</b>
First Registrationdate:	<b>6/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>137928</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

Options			
GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear			
Summer tyres:	<b>205/55/16/91 V LightMetal</b>		
	Fr.L.	Fr.R.	
	<b>Continental: 5 mm</b>	<b>Continental: 5 mm</b>	
	Re.L.	Re.R.	
	<b>Michelin: 6 mm</b>	<b>Michelin: 6 mm</b>	

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1201,88</b>
Alloy rim F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing R L, Bump(s) and scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Luggage space cover, Damaged, E - Replace			<b>240,00</b>

Bumper R, Scratch(es), LI - Repair and paint (complete)			<b>211,80</b>



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Door F R, Bump(s), Acceptable 0,00

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Rocker panel inner R R, Bump(s), Acceptable 0,00

No pictures to display

Ceiling, Dirty, Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Roof, Bump(s), Acceptable 0,00

No pictures to display

Side window R R, Damaged, E - Replace 75,00





Bumper F L, Scratch(es), It - Spot repair 115,56



Alloy rim R R, Scratch(es), I - Repair 100,00

