


AUDI A6: 1GTQ171

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnnumber: | WAUZZZ4G0EN122504 | Versionname: | A6 BER Multitr.136PK Aut. |
| First Registrationdate: | 25/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 167146 | Power Kw: | 100 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3603 |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | | Seats electric F R | |
| GPS storage | HD | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | Tow bar fixed |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting LED | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/17/101 V LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 7 mm | Re.R. | Michelin: 7 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 150,00 |
|-------------------|---------------|

| | |
|---|-------------|
| Wing F L, Scratch(es), LI - Repair and paint (complete) | 0,00 |
|---|-------------|



| | |
|---|-------------|
| Door F R, Scratch(es), LI - Repair and paint (complete) | 0,00 |
|---|-------------|



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 0,00



| | |
|--|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|--|------|



| | |
|---|--------|
| Certificate Of Conformity, Missing, E - Replace | 150,00 |
|---|--------|

No pictures to display