


AUDI A3: 1GAA480

Vinnumber:	WAUZZ8V4EA100084	Versionname:	A3 SB Ambiente S-tr.140PK Aut.
First Registrationdate:	3/12/2013	Fiscalpower:	
Expertise Mileage:	62354	Power Kw:	103
Bodytype:	Hatchback	Body color:	Light Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2108
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	250/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			866,55
Rocker panel inner R R, Bump(s), Acceptable			0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------





Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20

