


**AUDI A3: 1GPB863**

Vinnumber:	<b>WAUZZZ8V6EA158794</b>	Versionname:	<b>A3 SB Attraction 105PK</b>
First Registrationdate:	<b>24/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>81850</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/98 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Total cost ex VAT	2357,94
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20



Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Roof, Bump(s), PDR - Knock out without painting 280,80



Windscreen, Stone chip(s), E - Replace 487,20



Rear bulkhead lining, Scratch(es), E - Replace 62,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Bump(s), PDR - Knock out without painting 102,60



Rearview mirror R complete, Scratch(es), Smart repair 110,64



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Tailgate, Bump(s), PDR - Knock out without painting	63,00
---	-------

