


AUDI A1: 1EZL397

Vinnnumber:	WAUZZZ8X0DB104935	Versionname:	A1 5B Attraction 90PK
First Registrationdate:	29/04/2013	Fiscalpower:	
Expertise Mileage:	91703	Power Kw:	66
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2719
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/15/88 V LightMetal			
Summer tyres:	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1399,26
-------------------	----------------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	---------------



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	248,40
---	---------------





Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00




Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete) 385,20

