


BMW 3: 1EMA166

Vinnumber:	WBA3K91090F868227	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	18/01/2013	Fiscalpower:	
Expertise Mileage:	96469	Power Kw:	85
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3511
Maintenance:	1/03/2018		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1589,38
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Alloy rim R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door panel R L, Tear, E - Replace 114,00



Maintenance, Maintenance, Execute 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80




Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 50,00





Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), PDR - Knock out without painting	75,00

