



BMW 3 GRAN TURISMO: 1LSX190

Vinnnumber:	WB8Y51000G436813	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	26/11/2015	Fiscalpower:	
Expertise Mileage:	31350	Power Kw:	100
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3626
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/18/95 H LightMetal			
Summer tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		3116,99
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00



Interior, Dirty, Cleaning		50,00
---------------------------	--	-------




Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Roof pillar R, Chemical polution, LI - Repair and paint (complete) 220,18



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00





Door R L, Chemical pollution, LI - Repair and paint (complete) 318,35



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35

