



AUDI Q5: 1GHC956			
Vinnumber:	<b>WAUZZZ8R1EA081156</b>	Versionname:	<b>Q5 Quattro 150PK</b>
First Registrationdate:	<b>6/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>159324</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Radio CD		Seats electric F L	
GPS storage	<b>DVD</b>	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
Winter tyres:	<b>235/60/18/103 V LightMetal</b>			
	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

Assistance equipment	
Total cost ex VAT	1850,70
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	430,02



Bodywork, Damaged, Acceptable 0,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 430,02



Windscreen, Bad repair, E - Replace 560,64



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 430,02



Interior, Damaged, E - Replace 0,00

