


BMW SERIE 1: 1GRP488

Vinnumber:	WBA1C91040J524290	Versionname:	116d Eff.Dyn.Ed.
First Registrationdate:	9/04/2014	Fiscalpower:	
Expertise Mileage:	79980	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	IN 9000 KM		
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	296,90
-------------------	--------

Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Dashboard, Not functioning (well), P - Check	0,00
--	------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tires, Not original part, P - Check 0,00



Interior, Damaged, E - Replace 85,10



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, No damage, P - Check 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display