



BMW 3: 1GTU805			
Vinnnumber:	WBA3D91090J414261	Versionname:	3 BER 316d 116PK
First Registrationdate:	28/04/2014	Fiscalpower:	
Expertise Mileage:	114229	Power Kw:	85
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2707
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		




Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			261,80
Bonnet, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Bump(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bodywork, Glue residues, Remove lettering			25,00



Windscreen, Stone chip(s), Acceptable			0,00
---------------------------------------	--	--	-------------

<i>No pictures to display</i>		
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)		211,80
		
		
Roof, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Seat cover R R, Dirty, Cleaning		25,00
		
Bumper R, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		