



CITROEN DS3: 1CXG832

Vinnnumber:	VF7SA9HPKCW533009	Versionname:	DS3 BER eHDi Bus.GPS FAP 92PK
First Registrationdate:	19/03/2012	Fiscalpower:	
Expertise Mileage:	148009	Power Kw:	68
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1702
Number of doors:	3		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/16/87 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1222,58


Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bad repair, Acceptable 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Engine protective plate, Hole, E - Replace 64,00

