


FORD Kuga: 1EUN632

Vinnumber:	WF0AXXWPMACS45580	Versionname:	KUGA 2WD Titanium
First Registrationdate:	25/03/2013	Fiscalpower:	136PK
Expertise Mileage:	198094	Power Kw:	100
Bodytype:		Body color	Light Green
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/17/103 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Bridgestone: 1 mm	Re.R.	Bridgestone: 1 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	860,54
-------------------	--------

Wing moulding F L, Scratch(es), E - Replace	14,40
---	-------



Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Wing moulding F R, Scratch(es), Acceptable 0,00

No pictures to display

Supplementary brake lights, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Repaired, P - Check 0,00



Spoiler R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 235,80



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s), LI - Repair and paint (complete) 244,18



Centre console, Incomplete, E - Replace 5,00



Engine, Tear, E - Replace 45,98

