



FORD Fiesta: SM8215			
Vinnnumber:	WF0DXXGAKDEL75988	Versionname:	FIESTA BER Trend ECONetic S/S 95PK
First Registrationdate:	24/01/2014	Fiscalpower:	
Expertise Mileage:	143139	Power Kw:	70
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3515
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	175/65/14/82 T Steel		
	Fr.L.	Fr.R.	Michelin: 5 mm
	Re.L.	Re.R.	Michelin: 6 mm

Assistance equipment	
Spare wheel	Yes

Total cost ex VAT	1606,50
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44



Front bumper, Damaged, LI - Repair and paint (complete)	169,44
--	---------------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 246,56



Interior, Dirty, Cleaning 50,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display
Wing F L, Bump(s), LI - Repair and paint (complete) 176,14



Gear shift lever knob, Damaged, E - Replace 96,00



Front bumper, Incomplete, E - Replace 50,00



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F R, Damaged, E - Replace 24,00



Rocker panel inner R R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68

