



LEXUS CT200H: 1NKE844

Vinnnumber:	JTHKD5BH602268695	Versionname:	1.8 200H F-SPORT LINE
First Registrationdate:	9/03/2016	Fiscalpower:	AUTO
Expertise Mileage:	56221	Power Kw:	73
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	3407
Maintenance:	16/01/2018		
Maintenance:	48180		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/45/17/87 W LightMetal			
Summer tyres:	Fr.L.	Yokohama: 5 mm	Fr.R.	Yokohama: 5 mm
	Re.L.	Yokohama: 5 mm	Re.R.	Yokohama: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	95,00
-------------------	-------

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim R L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	