


LEXUS NX: 1LKL117

Vinnnumber:	JTJBJRBZ102025657	Versionname:	2.5 300H EXECUTIVE LINE
First Registrationdate:	13/10/2015	Fiscalpower:	4WD AUTO
Expertise Mileage:	57976	Power Kw:	145
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/18/100 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	95,00
-------------------	-------

Front bumper, Bump(s), Acceptable	0,00
-----------------------------------	------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim R L, Scratch(es), Acceptable 0,00



Door F R, Bump(s) and scratch(es), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00



Door R L, Bump(s) and scratch(es), Acceptable 0,00



Wing R R, Bump(s), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

