



MERCEDES A: 1ERM347			
Vinnumber:	WDD1760121J075332	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	1/03/2013	Fiscalpower:	
Expertise Mileage:	185511	Power Kw:	80
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3719
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			848,96
Steering wheel, Worn, Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rear spoiler, Scratch(es), LI - Repair and paint (complete)			115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00
--	--	--	-------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Damaged, E - Replace 235,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display