



**LAND ROVER Discovery: DH9522**

Vinnumber:	<b>SALLAAAG6EA708544</b>	Versionname:	<b>DISCOVERY 4 SDV6 HSE 256PK Aut.</b>
First Registrationdate:	<b>30/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>108161</b>	Power Kw:	<b>188</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1123</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Seats R heated
TV/DVD screen R	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>
Level control	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>255/55/19/111 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 2 mm</b>	Fr.R.	<b>Pirelli: 2 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>2926,32</b>
-------------------	----------------

Door F L, Scratch(es), LI - Repair and paint (complete)	<b>382,02</b>
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>254,16</b>
---	---------------



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Door R L, Scratch(es), LI - Repair and paint (complete)

382,02



Moulding windscreen U, Scratch(es), E - Replace

172,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar L, Scratch(es), LI - Repair and paint (complete)

264,22



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02

