



FORD TRANSIT COURIER: 1KGL685

Vinnumber:	WF0WXXTACWFD50911	Versionname:	1.6 TDCI 71KW TREND
First Registrationdate:	28/04/2015	Fiscalpower:	
Expertise Mileage:	165839	Power Kw:	71
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2523
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	
GPS storage	SD
Windows electric F	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/15/88 T LightMetal			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT

	801,21
--	---------------

Front bumper, Scratch(es), LI - Repair and paint (complete)

	158,85
--	---------------



Trunk door R R, Bump(s), PDR - Knock out without painting

63,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Trunk door R L, Scratch(es), LI - Repair and paint (complete) 115,00



Door R R, Bump(s), PDR - Knock out without painting 82,80



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F L, Bump(s), PDR - Knock out without painting 63,00



Interior, Stain, Cleaning 25,00



Door F R, Bump(s), Acceptable 0,00

No pictures to display

Sidewall FL (LCV), Bump(s), PDR - Knock out without painting 115,00



Bumper R, Bump(s), Acceptable 0,00

No pictures to display