



| MERCEDES A: 1JHT480                |                          |              |                      |
|------------------------------------|--------------------------|--------------|----------------------|
| Vinnnumber:                        | <b>WDD1760121V047032</b> | Versionname: | <b>1.5 A 180 CDI</b> |
| First Registrationdate:            | <b>23/12/2014</b>        | Fiscalpower: |                      |
| Expertise Mileage:                 | <b>52582</b>             | Power Kw:    | <b>80</b>            |
| Bodytype:                          |                          | Body color:  | <b>Black</b>         |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>       |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>     |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>            |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1610</b>          |
| Number of doors:                   | <b>5</b>                 |              |                      |
| Number of seats:                   | <b>5</b>                 |              |                      |
| Number head rests:                 | <b>5</b>                 |              |                      |
| Rims summer:                       | <b>Aluminium</b>         |              |                      |
| Category:                          | <b>Passenger Car</b>     |              |                      |
| Oil level:                         | <b>OK</b>                |              |                      |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                      |

| Options                        |                                       |
|--------------------------------|---------------------------------------|
| Radio CD                       | Central consol F                      |
| Windows electric F             | Luggage cover                         |
| Windows electric R             | Front parking sensors                 |
| Cruise Control                 | Rear parking sensors                  |
| Steering wheel multifunctional |                                       |
| Radio multimedia               |                                       |
| Type of headlighting           | <b>Headlighting Xenon</b>             |
| Type of GPS                    | <b>GPS big screen color</b>           |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |
| Type of climate control        | <b>Manual climate control</b>         |







| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                    | <b>OK</b> | Transmission        | <b>OK</b>  |
|                              |           | Lighting            | <b>OK</b>  |
|                              |           | Wiperblades         | <b>OK</b>  |

| Degree of wear |                                  |                       |       |                       |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
|                | <b>225/40/18/92 V LightMetal</b> |                       |       |                       |
| Summer tyres:  | Fr.L.                            | <b>Uniroyal: 7 mm</b> | Fr.R. | <b>Uniroyal: 7 mm</b> |
|                | Re.L.                            | <b>Uniroyal: 8 mm</b> | Re.R. | <b>Uniroyal: 8 mm</b> |

| Assistance equipment  |            |            |            |
|---|------------|------------|------------|
| Repair kit  | <b>Yes</b> | Compressor | <b>Yes</b> |
| Total cost ex VAT   |            |            | 1291,91    |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) |            |            | 95,00      |



|                                   |      |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

|  |        |
|--|--------|
| Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)             | 115,56 |
|      |        |
| Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)                  | 308,20 |
|    |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete)                              | 211,80 |
|     |        |
| Alloy rim R R polished, Scratch(es), Acceptable                                      | 0,00   |
| <i>No pictures to display</i>  |        |
| Alloy rim R L polished, Scratch(es), Acceptable                                      | 0,00   |
| <i>No pictures to display</i>  |        |
| Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)                | 95,00  |
|   |        |
| Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)                  | 318,35 |
|  |        |
| Window F R door, Scratch(es), E - Replace  | 148,00 |
|   |        |