



RENAULT Clio: 1GQQ527			
Vinnumber:	VF17RFL0H50557970	Versionname:	CLIO IV BRE Energy Expression 90PK
First Registrationdate:	2/04/2014	Fiscalpower:	
Expertise Mileage:	152678	Power Kw:	66
Bodytype:	Break	Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1105
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			
	784,72		
Door F R, Scratch(es), LI - Repair and paint (complete)			
	254,68		



Mirror side blinker R, Damaged, E - Replace	28,80
---	--------------



Front bumper, Bad repair, Acceptable	0,00
--------------------------------------	-------------



Roof pillar L, Bump(s), Acceptable	0,00
------------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Internal Boot Lining R, Damaged, Acceptable	0,00
---	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	--------

