


OPEL Zafira: 1EWM335

Vinnumber:	W0LPE9EM0D2047635	Versionname:	ZAFIRA TOURER
First Registrationdate:	8/04/2013	Fiscalpower:	ecoFL.Cosmo St/St.130PK
Expertise Mileage:	175677	Power Kw:	96
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	708,30
-------------------	--------

Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

						Foglight L, Scratch(es), E - Replace	138,00	
						Door R R, Scratch(es), Acceptable	0,00	
						Bumper R, Scratch(es), Acceptable	0,00	
							Wing R R, Scratch(es), Acceptable	0,00
						Floor covering F L, Worn, P - Check	0,00	
						Trunk lid covering R, Scratch(es), Acceptable	0,00	
						Maintenance book, Missing, E - Replace	0,00	
					Sill outer R, Bump(s), LI - Repair and paint (complete)	358,50		