


PEUGEOT 508: 1DVU346

Vinnnumber:	VF38DRHR8CL060363	Versionname:	508 BER Active 136PK
First Registrationdate:	12/09/2012	Fiscalpower:	
Expertise Mileage:	188318	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2309
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	436,98
-------------------	--------

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display


Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bump(s), PDR - Knock out without painting	63,00



Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Windscreen repair	58,80



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	