


MERCEDES E: 1EZW989

Vinnumber:	WDD2122051A797589	Versionname:	E BRE 200CDI BE
First Registrationdate:	2/05/2013	Fiscalpower:	Start/Stop 136PK
Expertise Mileage:	123576	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3206
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/17/99 Y LightMetal			
Summer tyres:	Fr.L.	Goodyear: 8 mm	Fr.R.	Goodyear: 8 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			95,00
Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Chemical pollution, Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Maintenance book, Missing, E - Replace			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Interior, Dirty, Cleaning 0,00

