



## PEUGEOT Partner: 1GRF137

Vinnumber:	<b>VF37F9HF0EJ614052</b>	Versionname:	<b>PARTNER B/F L2H1</b>
First Registrationdate:	<b>7/04/2014</b>	Fiscalpower:	<b>Conf.121 90PK</b>
Expertise Mileage:	<b>102070</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>100150 KM</b>	Parking lot:	<b>3331</b>
Maintenance:	<b>4/07/2017</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	
Windows electric F	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Other: 7 mm</b>	Fr.R.	<b>Other: 7 mm</b>
	Re.L.	<b>Other: 6 mm</b>	Re.R.	<b>Other: 6 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	360,13
Wing F L, Scratch(es), LI - Repair and paint (complete)	165,13



Sliding door R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, P - Check	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	22,50



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Trunk door R L, Bump(s) and scratch(es), Acceptable 0,00

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace 22,50



Ignition key, Missing, E - Replace 150,00



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*