



MERCEDES C: 1HHG865

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnnumber: | WDD2050041F057006 | Versionname: | C BER 220 BlueTEC 163PK |
| First Registrationdate: | 23/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 185068 | Power Kw: | 120 |
| Bodytype: | Berline | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3622 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Front parking sensors |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/60/16/92 V LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 984,06 |
| Front bumper, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



| | | | |
|--|--|--|--------------|
| Wing R R, Bump(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 292,18



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08

