



RENAULT Megane: 1FVB474

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber: | VF1BZ1A0749472960 | Versionname: | MEGANE BER Authentique 90PK |
| First Registrationdate: | 4/11/2013 | Fiscalpower: | |
| Expertise Mileage: | 60173 | Power Kw: | 66 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3633 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|-----------------------|-----------------------------|
| Radio CD | Luggage cover |
| Windows electric F | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining fabrics |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | |
|-----------------------------|----------------------|----------------------|--|
| 195/65/15/91 T Steel | | | |
| Summer tyres: | Fr.L. Michelin: 4 mm | Fr.R. Michelin: 4 mm | |
| | Re.L. Michelin: 5 mm | Re.R. Michelin: 5 mm | |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|---|---------|
| Total cost ex VAT | 3016,96 |
| Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |



| | |
|---|-------|
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |
|---|-------|



| | |
|---|--------|
| Door moulding Lower R R, Scratch(es), E - Replace | 114,00 |
|---|--------|



Steering wheel, Worn, Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20





















Interior, Dirty, Cleaning 50,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Wheel cover R L - Scratch(es), Acceptable 0,00

| | | |
|---|---|--|
| <i>No pictures to display</i> | | |
| Wheel cover F L, Broken, E - Replace | | 30,00 |
|  |  | |
| Bumper R, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door F R, Scratch(es), LI - Repair and paint (complete) | | 318,35 |
|  |  |  |
| Wheel cover R R, Broken, E - Replace | | 30,00 |
|  |  | |
| Backrest cover F L, Tear, E - Replace | | 360,00 |
|  |  | |
| Bodywork, Not original part, Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Ignition key, Not functioning (well), Forfeit | | 0,00 |
| <i>No pictures to display</i> | | |
| Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) | | 314,08 |
|  |  |  |
|  |  | |
| Sill outer R, Bump(s) and scratch(es), Le - Replace and paint | | 712,00 |
|  |  |  |
|  | | |