


RENAULT Grand Scenic: 1EHW124

| | | | |
|-------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber: | VF1JZ14A648184028 | Versionname: | GR.SCENIC Energ.Business |
| First Registrationdate: | 7/12/2012 | Fiscalpower: | 5pl.FAP 110PK |
| Expertise Mileage: | 189982 | Power Kw: | 81 |
| Bodytype: | Hatchback | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | NOT OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|--------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | SD Rear parking sensors |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | 205/60/16/96 H Steel | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 8 mm | Re.R. | Michelin: 8 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|--|--------|
| Total cost ex VAT | 858,04 |
| Wheel cover F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Bump(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tailgate, Scratch(es), It - Spot repair | 115,56 |



| | |
|---|--------|
| Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|---|------|
| Roof, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|--|------|
| Wheel cover R L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|-------|
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |
|---|-------|



| | |
|---|------|
| Door F R, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---|------|
| Door catch R R, Scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 350,68 |
|---|--------|



| | |
|---|--------|
| Registration Document, Missing, E - Replace | 150,00 |
|---|--------|

No pictures to display

| | |
|-------------------------------|------|
| Door F L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display