



OPEL Astra: 1HLH303

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | WOLPE8E30E8060451 | Versionname: | ASTRA BRE ecoFLEX Cosmo 136PK |
| First Registrationdate: | 19/08/2014 | Fiscalpower: | |
| Expertise Mileage: | 139338 | Power Kw: | 100 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3819 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD | | Sun Roof electric | |
| GPS storage | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| Windows electric F | | Front parking sensors | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | Tow bar fixed |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 215/60/16/99 H LightMetal | | | |
| Winter tyres: | Fr.L. | Goodyear: 7 mm | Fr.R. | Goodyear: 7 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 626,10 |
|-------------------|--------|

| | |
|---|--------|
| Rearview mirror L complete, Broken, E - Replace | 168,00 |
|---|--------|



| | |
|---|--------|
| Wing R L, Chemical polution, LI - Repair and paint (complete) | 308,20 |
|---|--------|



Tailgate, Bump(s), PDR - Knock out without painting 63,00



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Inner seat cover L, Broken, E - Replace 23,90



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display