



PEUGEOT 508: 1EHW140

Vinnnumber:	VF38E9HD8CL085655	Versionname:	508 SW e-HDi Active BMP 115PK Aut.
First Registrationdate:	7/12/2012	Fiscalpower:	
Expertise Mileage:	206611	Power Kw:	84
Bodytype:	Break	Body color:	Light Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3424
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Type of headlighting	Headlighting Halogen	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining semi-leather	Type of Tow bar	Tow bar removable
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel **Yes**

Total cost ex VAT **274,80**

Door F L, Scratch(es), LI - Repair and paint (complete) **0,00**



Door R L, Scratch(es), LI - Repair and paint (complete) **0,00**



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------




Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display