



VOLKSWAGEN Polo: 1EQV947

Vinnnumber:	WVWZZZ6RZDY122480	Versionname:	POLO Comfortline DPF
First Registrationdate:	26/02/2013	Fiscalpower:	75PK
Expertise Mileage:	118434	Power Kw:	55
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1233
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 T Steel			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	441,44
Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44



Wheel cover R L, Scratch(es), E - Replace	24,00
---	--------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display


Door panel R R, Damaged, E - Replace 96,00



Rearview mirror housing L, Damaged, E - Replace 64,00



Protection plate M, Tear, E - Replace 64,00



Wheel cover R R, Scratch(es), E - Replace 24,00



Bonnet, Bad repair, Acceptable 0,00

