


**TOYOTA Yaris: 1GDZ649**

Vinnnumber:	<b>VNKKD3D310A068005</b>	Versionname:	<b>YARIS BER Hybrid Comfort</b>
First Registrationdate:	<b>13/01/2014</b>	Fiscalpower:	<b>74PK Aut.</b>
Expertise Mileage:	<b>15896</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3114</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>175/65/15/84 H Steel</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 4 mm</b>	Re.R.	<b>Dunlop: 4 mm</b>

**Assistance equipment**


Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>192,00</b>
-------------------	---------------

Door R L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*


Door panel R R, Scratch(es), E - Replace	<b>96,00</b>
--	--------------



Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

*No pictures to display*

Wing R R, Bad repair, Acceptable	<b>0,00</b>
----------------------------------	-------------



Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Scratch(es), E - Replace	96,00

