



RENAULT Megane: 1EXW908

Vinnumber:	VF1KZ1A0748993578	Versionname:	MEGANE GT TomTom Edition 90PK
First Registrationdate:	17/04/2013	Fiscalpower:	
Expertise Mileage:	138031	Power Kw:	66
Bodytype:	Break	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3233
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 V Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1556,80
-------------------	----------------

Wheel cover F R, Scratch(es), E - Replace	30,00
---	--------------



Wheel cover R L, Broken, E - Replace	30,00
--------------------------------------	--------------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	--------------



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Mirror side blinker L, Damaged, E - Replace 30,00




Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Bump(s), LI - Repair and paint (complete) 310,50



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Rearview mirror housing R, Scratch(es), E - Replace 84,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

