



RENAULT MEGANE GRANDTOUR: 1LSD095

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber: | VF1KZ890H53978936 | Versionname: | 1.5 ENERGY DCI 110 LIMITED |
| First Registrationdate: | 19/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 39867 | Power Kw: | 81 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | NOT OK | Parking lot: | 3104 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|--------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | SD Rear parking sensors |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Tires wear profile | OK | Battery functioning | Yes |
| Idle position | OK | Power steering | Yes |
| Engine startingtime | OK | Sound engine | OK |
| Exhaust gass | OK | Clutch test | OK |
| Handbrake | OK | Wiper fluid level | OK |
| | | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 H LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 158,00 |
|-------------------|---------------|

| | |
|---|-------------|
| Rear Panel Internal Lining, Scratch(es), Acceptable | 0,00 |
|---|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Maintenance, Maintenance, Execute | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---|--------------|
| Tailgate, Bump(s), PDR - Knock out without painting | 63,00 |
|---|--------------|



| | |
|--|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|

